



Air Compressor Hook Up Kit

INSTRUCTIONS • #004-527

Use entire 50 ft. length of #050-004 Tubing. Coil excess as shown.

Part #	Description
050-004	Tubing 50 ft.
022-231	Connector (2 qty.)
002-379	Bushing



GraverMach AT Not Included.

GLENDO LLC

900 Overlander Road • Emporia, KS 66801 USA
800-835-3519 • 620-343-1084 • Fax 620-343-9640
hello@grs.com • www.grs.com
Last Updated: 08/10/2023

LIT-001